civacon™
AN OPW® FLUID TRANSFER GROUP COMPANY

873 4" Dust Cap (aluminum)

Replacement Parts

Rev. 0, January 2003



ITEM	PART NUMBER	DESCRIPTION	QTY.
1	SC02614A	CAP (ALUMINUM)	1
2	H08347M	GASKET (BUNA)	1
3	H08328M	CONNECTOR RING	1
4	H20144M	GROOVE PIN	2

ITEM	PART NUMBER	DESCRIPTION	QTY.
5	H20325M	CHAIN	1
6	D10184M	CAM ARM	2
7	H20550M	FINGER RING	2

OBSOLETE PART - SEE 875C
REPAIR PARTS STILL AVAILABLE

874 4" Dust Cap (duratuff)



ITEM	PART NUMBER	DESCRIPTION	QTY.
1	D10061P	CAP (DURATUFF)	1
2	H08347M	GASKET (BUNA)	1
3	H08328M	CONNECTOR RING	1
4	H20144M	GROOVE PIN	2

ITEM	PART NUMBER	DESCRIPTION	QTY.
5	H20325M	CHAIN	1
6	H20377M	ROLLER	1
7	H20378	CAM ARM ASSEMBLY	1

civacon™
PHONE: (816) 741-6600 • (888) 526-5657 • Fax: (816) 741-1061
4304 Mattox Road • Kansas City, MO 64150 • **www.civacon.com**