

## SiteSentinel® iSite™ Maintenance Kit

Part #4407

The hardware maintenance kit includes a USB key and a USB mouse. The two USB devices can be plugged into either of the external USB ports on the left hand side

of the SiteSentinel® iSite™ console. The two devices will be used in the event of system failure or retrieving key troubleshooting files



USB Key (part #S002003)



Mouse (part #75-0109)

The USB mouse will be used in the event of the touch screen losing calibration, failure to be calibrated or touch screen failure. This will allow the navigation of the mouse to get the screen back into working order.

The USB key contains a file that will be used to access the windows portion of the SiteSentinel™ iSite™ console or view the running log file as shown below. This key will not be used on a regular basis. In the event of a system problem that cannot be solved over the phone, the user will insert the key into the external USB port on the console and wait a few seconds. After this period of time, the user will have access to browse the Windows platform. From here the user will be able to retrieve files to send to the manufacturer for evaluation. After the files are removed, the user will remove the key and the system will return back to a normal state after a few seconds.

```
Apr 15 11:18:35 WindowsCE ota/pnet1[e492f8d2]: shutting down
Apr 15 11:18:37 WindowsCE OTA[6510b7a2]: pnhost: register unit [B4]
Apr 15 11:18:37 WindowsCE OTA[6510b7a2]: pnhost: register unit [V1]
Apr 15 11:18:37 WindowsCE OTA[6510b7a2]: pnhost: register unit [V2]
Apr 15 11:18:37 WindowsCE OTA[6510b7a2]: pnhost: register unit [I1]
Apr 15 11:18:37 WindowsCE OTA[6510b7a2]: pnhost: add product probe 561200 SN: 10458
Apr 15 11:18:37 WindowsCE OTA[6510b7a2]: pnhost: add product probe 561400 SN: 1469389-Q06
Apr 15 11:18:37 WindowsCE OTA[6510b7a2]: pnhost: add product probe 561500 SN: 1473010-R04
Apr 15 11:18:37 WindowsCE OTA[6510b7a2]: pnhost: add product probe 561600 SN: 0922040100
Apr 15 11:18:37 WindowsCE OTA[6510b7a2]: pnhost: add product probe 561700 SN: 120114-A02-0708
Apr 15 11:18:37 WindowsCE OTA[6510b7a2]: pnhost: add product probe 562000 SN: 10459
```