




1986 3" Vapor Vent

Replacement Parts

Rev. 0, January 2003



ITEM	PART NUMBER	DESCRIPTION	QTY.
1	E10162A	BODY	1
2	C10045A	POPPET	1
3	H20749M	SEAT DISC (VITON) ¹	1
4	H20516M	PLUG ¹	1
5	11772	PISTON ¹	1
6	FF11AA	SEAL (BUNA U-CUP) ¹	2
7	H20066M	RETAINING RING	1
8	H20249M	O-RING (BUNA) ¹	1
9	H05487M	WASHER (FLAT)	1
10	H20517M	BEARING	1

ITEM	PART NUMBER	DESCRIPTION	QTY.
11	H52179M	SPRING	1
12	H20070M	CAP SCREW	1
13	H04467M	WASHER (LOCKING)	1
14	H20124M	O-RING (VITON)	1
15	H20083M	LOCKING RING	1
16	H20123M	SET SCREW	1

REPAIR KITS		
PART NUMBER	DESCRIPTION	QTY.
1986RK	VENT REPAIR KIT	N/A

1 - Included in 1986RK