




1985 3" Vapor Vent

Replacement Parts

Rev. 0, January 2003



ITEM	PART NUMBER	DESCRIPTION	QTY.
1	E10157A	BODY	1
2	C10010A	POPPET	1
3	H20750M	SEAT DISC (VITON) ¹	1
4	H20516M	PLUG ¹	1
5	11772	PISTON ¹	1
6	FF111A	SEAL (BUNA U-CUP) ¹	2
7	H20066M	RETAINING RING	1
8	H20249M	O-RING (BUNA) ¹	1
9	H05487M	WASHER (FLAT)	1
10	H20517M	BEARING	1

ITEM	PART NUMBER	DESCRIPTION	QTY.
11	H52179M	SPRING	1
12	H20070M	CAP SCREW	1
13	H04467M	WASHER (LOCKING)	1
14	C10011M	FLANGE GASKET	1
15	H20074M	SEAL WASHER	8
16	H20518M	CAP SCREW	8

REPAIR KITS		
PART NUMBER	DESCRIPTION	QTY.
1985RK	VENT REPAIR KIT	N/A

1 - Included in 1985RK