

Midland Manufacturing
7733 Gross Point Road
Skokie, Illinois 60077, USA
Tel: (847) 677-0333

TECHNICAL SERVICE BULLETIN (TSB) 20250321-02 Issued March 21, 2025

23-8-SS & 23-8-SC Locknut Replacement

UPDATE: Clarification on the 23-82-MO Wedge Lock Washer


Items Affected: A-2000 PRVs & Repair Kits, A-3000 PRVs & Repair Kits, and A-800 Pressure Vacuum Valves & Repair Kits.

Summary: The 23-8-SS & 23-8-CS locknuts are being discontinued due to ongoing supply chain issues.

Beginning March 21, 2025, these locknuts are being transitioned to the following two items:

- 23-81-SS: THIN HEX NUT, 3/4-16, 18-8 STAINLESS STEEL
- 23-82-MO: WEDGE LOCK WASHER, 316 STAINLESS STEEL
 - This wedge lock washer consists of two pieces. See drawing below.
 - Placing an order for (1) 23-82-MO will include (2) pieces, or (1) set.
 - The Torque specification remains unchanged from the 23-8-SS & 23-8-CS specification.

While this transition takes place, repair kits and assemblies may arrive supplied with either solution as we work through remaining inventory of 23-8-SS & 23-8-CS. This transition should be complete by the end of April 2025.



Contact Us: For additional questions, visit:

<https://www.opwglobal.com/midland/contact/sales-manager-locator> for contact information.

This TSB is based on extensive testing and performance experience and is the most current information available. Midland reserves the right to make changes in specifications and other information contained in this document without prior notice. The users should in all cases consult Midland to determine whether any such changes have been made.