

OPW LOADING-RACK EQUIPMENT

Convenient and Simple to Order

OPW has made it easy and convenient for you to select loading-rack ground verification equipment for your operations. We have reduced the complexity of ordering by offering a standard package.

Features and Benefits

- · Easy to install and use
- Chassis is contained in a small explosion-proof enclosure
- Clamp's carbide-tipped contacts bite through paint and rust to ensure proper grounding
- · LED lamps for long life and reliability
 - · 100,000-hour minimum
- Suitable for top and bottom loading
- Backed by OPW's warranty and guarantee
- OPW technical support service


For additional options, see our rack-equipment sales guide.



Call (800) 547-9393 for more information.



Tank-Truck Grounding Solutions





OPW recommends the use of our Junction Boxes for all installations. In the event of a pull away or damaged ground clamp, the Junction Box allows for fast, easy repairs without the need to turn off power or open the explosion-proof housing. Getting the rack back operating quickly.

The OPW Grounding Solutions Package Includes:



8030-120*

Ground Verification Monitor with Red/Green Status Lights, 120-Volt

2

7500-7500 **Junction Box**

for Optic, Thermistor and Ground Verification Plug & Cord Sets (Non-Breakaway)



7720-7720

Ground Verification Clamp

with 40' straight cord

Part No.: OPW-GRND1

*also available in 240V version (Package p/n OPW-GRND2)

Ordering Comparison Chart

Part Number		
OPW	Scully	Description
8030-120	08820	Ground Verification Monitor, 120 Volt
8030-240	08508	Ground Verification Monitor, 240 Volt
7500-7500	32319	Junction Box for Optic, Thermistor and Ground Verification
7720-7720	32665	Clamp and Cable Assembly, 40' Straight Cable
7720-COIL	31766	Clamp and Cable Assembly, 30' Coiled Cable

CONTACT YOUR SALES REPRESENTATIVE FOR MORE INFORMATION OR CALL (800) 547-9393.

