

Page 1 of 3 - 8/6/2020

OPW Fuel Management Systems - Phoenix Lite Copyright (C) 2019-2020 OPW Fuel Management Systems All Rights Reserved

This document provides information about known issues, fixes and new features that are available in this release.

Release Version: 1.16.13.13 (Install release) 4/19/18

****** New features Added to this Patch Release ******

Updated installation process in support of Windows 10 (32/64 bit) and Windows 2016 server. When not available, installation provides SQL Server Express 2014.

****** Problems and Known Issues Resolved in this Patch ******

No known issues

Release Version: 1.15.12.12 (2/21/18)

****** New features Added to this Patch Release ******

Added new card types, for card total report.

Updated Manual Transaction editing where the transaction's assigned Account number is changed to reflect the last Driver or Vehicle card number selection. This allows user to alter a transaction's billed account number.

Allow assignment of Single Cards to the Global Cards account.

Reversed default transaction view to display most current at top.

****** Problems and Known Issues Resolved in this Patch ******

Modified Fuel Zone deletion to decline request if zone is currently mapped to any card on file.

Updated support of SQL Server Services to ensure connection on start-up when SQL Server was installed during Phoenix installation.

Fixed error condition where ATG Last Poll results were not being properly updated.

Updated Password naming on site configuration page to match FSC references.

Fixed offline license activation error.

OPW Fuel Management Systems • 6900 Santa Fe Drive, Hodgkins, IL 60525 • Tel: (708) 485-4200 • https://www.opwglobal.com/opw-fms



Page 2 of 3 - 8/6/2020



Fixed issues related MPG calculations, associated to product settings and duplicated Transaction and Sequence number on same date.

Removed "Global Cards" account from dropdown selection under account report settings.

Added new printer tab to view the systems default printer. This can seen under: Settings->Configuration->Preferences.

Removed Decimal Point and Type field from the Custom Export page.

Fixed export concerns related to spacing and alignment issues.

Fixed certain reports that failed to generate due MPG formula error.

Fixed Quantity and Price rounding issue during import of polled transactions.

Fixed issue where reports selected for landscape printed as portrait.

• Requires SAP update 13.0.21 provided with this update.

Fixed issue where Service Engine was crashing when log file were changed to network directories.

• For logging reliability it is recommended that local directories are selected for use.

Fixed transaction reprice issue where values less than 1.000 were not allowed.

Resolved modem connection issues.

Fixed column alignment on some reports.

Fixed Status reporting issue for scheduler Reprice event.

Fixed condition where 5-digit IP port numbers where not supported.

Fixed issue when importing incomplete transactions after creating the missing cards. Caused some transactions to be lost.

Fixed issue when importing transactions from FSC USB k2500.trn file, when "***END***" line was missing.

Fixed issue where the "FSC Account" tab was available for edit when the FSC does Not use Account Cards feature was configured for use.

Fixed a resulting issue in date field of custom export where time was always shown as 12:00am.

OPW Fuel Management Systems • 6900 Santa Fe Drive, Hodgkins, IL 60525 • Tel: (708) 485-4200 • https://www.opwglobal.com/opw-fms





Fixed data validation issue in Tank Reconciliation Report.

Resolved issue where FSC command line allowed the configuration of longer password lengths.

Changed how Print option is available in reporting module.

Fixed issue where ATG polling would sometimes fail using FSC Pass-thru port over modem connections.

